



FLOORCOVERINGS

ATANDUS COMPANY

MAINTENANCE REQUIREMENTS

(Requisitos para el mantenimiento)

NOT APPROVED (NO ACEPTABLE)

APPROVED (ACEPTABLE)



NO Optical Brighteners
(Abrillantadores Ópticos)

NO Non-Approved Detergent
(No usar detergente no aceptable)

NO pH >9



NO cleaning solutions in extractor
(No soluciones limpiadoras en el extractor)



NO Bonnet Machines
(No usar maquinas de sombrerete "bonnet")



Only use hot water in extractor
(Solo usar agua caliente en el extractor)



Use Syon-5
(Usar Syon-5)



Pre-Spray with Syon-5
(Prerociar con Syon-5)

C&A SCHEDULED CLEANING (C&A Limpieza Programada)

Step 1

(Paso Uno)



Pre-Spray with SYON-5
(Prerociar con Syon-5)

Step 2

(Paso Dos)



Brush
(Cepillar)

Step 3

(Paso Tres)



Extract while wet
(Extraer mientras humeda)



OR
(o)

Vacuum when dry
(Aspirar cuando seca)

C&A SPOT CLEANING (C&A Tratado de Manchas)

Step 1

(Paso Uno)



Pre-Spray with SYON-5
(Prerociar con Syon-5)

Step 2

(Paso Dos)



Brush
(Cepillar)

Step 3

(Paso Tres)



Vacuum when dry
(Aspirar cuando seca)

OR
(o)



Extract while wet
(Extraer mientras humeda)

FOR APPROVED EQUIPMENT CONTACT (Para Equipo Contacte):

R.E. Whittaker Co. 800.422.7686
Windsor Industries, Inc. 303.762.1800

Nobles 800.522.7839
NSS Enterprises, Inc. 419.531.2121

FOR C&A TECHNICAL ASSISTANCE CONTACT (Para Asistencia Técnica Contacte):

C&A Floorcoverings 800.241.4902 ext. 2120
www.powerbond.com